

Date: Thursday, 02/10/2008 8:24:12 AM
 User: Julie Lecocq

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: OVERHEAD REAR, LH
Job Number	: 42389		
Estimate Number	: 13609		
P.O. Number	:	Part Number	: D38291
This Issue	: 02/10/2008	S.O. No.	:
Prsht Rev.	: NC	Drawing Number	: D38291 PROTOTYPE
First Issue	: //	Project Number	:
Previous Run	:	Drawing Revision	: PROTOTYPE
	Type : R&D THERMOFORMING	Material	: KYDEX 6185 (TBD)
Written By	:	Due Date	: 17/10/2008
Checked & Approved By	: <u>JLP 08.10.02</u>	Qty:	1 Um: Each
Comment	:		

Additional Product

PROTOTYPE

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	HAND FINISH TH	HAND FINISHING THERMOFORMING
	Comment: HAND FINISHING THERMOFORMING	
	1) Machine set up	
		<u>DL- 08.10.02</u>
2.0	HAND FINISH TH	HAND FINISHING THERMOFORMING
	Comment: HAND FINISHING THERMOFORMING	
	1) Cut sheet to required blank size	
		<u>DL- 08.10.02</u>
3.0	THERMOFORMING	THERMOFORMING MACHINE
	Comment: THERMOFORMING MACHINE	
	Thermoform as per Dwg. D3829-1 nd folio (FTA 9257Prototype) using tool DT 9257	
	Dwg. Rev. <u>PROTOTYPE</u>	
	Folio Rev. <u>A</u>	
		<u>DL- 08.10.02</u>
4.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
	Comment: INSPECT PARTS AS THEY COME OFF MACHINE	
	Visually inspect for proper formation of each part	
		<u>DL- 08.10.02</u>

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 02/10/2008 8:24:12 AM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: OVERHEAD REAR, LH

Job Number: 42389

Part Number: D38291

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

5.0

QC8

SECOND CHECK



Comment: SECOND CHECK

6.0

HAND FINISH TH

HAND FINISHING THERMOFORMING



Comment: HAND FINISHING THERMOFORMING

1) Trim to Finished Dimensions

PROTOTYPE

KEEP IN ENG'G LAB

PH
09.02.20

7.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Check dimensions to ensure conformity to drawing tolerances.

8.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

9.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: _____

10.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



00251A

for drawing 1
used per Dwg

11 09 02.24

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries